



Direction	1	2	3
Left	○	○	
Center			○
Right		○	○

Fuse	Rating
Main	30A
Relay	5A
Hour Meter	5A
Fuel Cut-off	5A
Work Lamp	10A
Swivel Valve	5A
Not Used	5A

Color Codes		
Black	-B	White -W
Red	-R	Green -G
Yellow	-Y	Brown -Br
Blue	-L	Orange -O
Pink	-P	Light Green -Lg
Violet	-V	Sty Blue -Sb

Example: WB (White/Black)

Wires are of AVS or CAVS type, of 0.5 size unless otherwise noted.

Swivel Lever Switch (Left)(Right)

Swivel Valve (Left) (Right)

Swivel Limiter Switch

Work Lamp (12V-55W)

Condition	Symbol
No Pressure	○
Pressured	●

Swivel Warning Release Switch

Oil Pressure Lamp

Fuel Meter (12V 16-55mA)

Swivel Warning Switch

Condition	C	NC	NO
Normal	○	○	○
Abnormal	○	○	●

Term.	B	ACC	C
OFF	○	○	○
ON	○	○	○
Start	○	○	○

Horn Switch

Condition	Symbol
OFF	○
ON	●

Condition	Symbol
Neutral	○
Lever Engaged	●

Condition	Symbol
Neutral	○
Lever Engaged	●

Stop Relay Horn Relay Starter Relay

Fuel Sensor

Relay Box

Regulator

Starter Motor

Battery