



見出	部品番号	部品名称		個数	型 寸	互換性	適用号機	備 考
NO.	PART NO.	PART NAME	Q'ty	DESCRIPTION	R/P	FROM ~ UP TO SERIAL NO.	REMARKS	
S01	5232 660A 999	ロフセット	ROPS set	1	S25A		号機連絡必要	
							Serial No. of machine required when ordering	
1		サポート	SUPPORT	1	S25A			
2	K712 0110 025	Fボルト	BOLT	12	M10*25 P=1.25			
4	A083 0110 001	ナット	NUT	12	M10 P=1.25			
56		マーク	MARK	1	S25A		ROPS宣言書 Certification of ROPS	
57	3677 5063 000	マーク	MARK	1			注意 Caution	
59	5232 5016 000	マーク	MARK	4			ツリ上げ禁止 Caution	
29	5232 3051 000	ブラケット	BRACKET	1			交換部品 Need to be Replaced with ROPS	
37	5232 3062 000	シートASSY	SEAT ASSY	1			交換部品 Need to be Replaced with ROPS	

注 1) S01 ROPS set (No.1, No.2, No.4, No.56, No.57, No.59を含む)にて供給。No.1, No.56は単品供給不可。
ROPS製造号機 と 本機製造号機 を管理しています。
ROPS set 注文の際には、本機製造号機を連絡願います。

注 2) ROPS仕様でない機体にROPSセットを取り付ける場合は、取り付け穴が必要となる場合があります。
それに加えNo.29, No.37の交換が必要です。(No.29, No.37は、ROPS setに含まれません。)

Note 1) ROPS can only be supplied as a complete set. Individual parts (No.1,2,4,56,57 and 59) can not be supplied. ROPS set can not be supplied without serial number of the main machine. Please give the serial number of the main machine when ordering as the serial numbers of the ROPS and the main machine need to be controled together.

Note 2) For the models without provisions for the ROPS, some drilling may be required. Parts No.29 and No.37 also need to be replaced.
(Parts number No.29 and No.37 are not included in the ROPS set.)